Please cite as: O.S. Bursi, T. Dusatti, R. Pucinotti (2009), *A Reconnaissance report. The April 6, 2009, L'Aquila Earthquake. Italy.* http://www.reluis.it

A RECONNAISSANCE REPORT. THE APRIL 6, 2009, L'AQUILA EARTHQUAKE. ITALY

by Oreste S. Bursi¹, Thomas Dusatti², Raffaele Pucinotti³,

oreste.bursi@ing.unitn.it; raffaele.pucinotti@unirc.it; t.dusatti@deltaingegneria.com

¹Department of Mechanical and Structural Engineering. University of Trento. Italy

SUMMARY

The 2009 L'Aquila Earthquake, a magnitude $M_{\rm w}$ 6.3 event struck L'Aquila and neighborhood, Italy, on Monday morning, April 6, 2009 at 01:32:39 UTC. L'Aquila is located at about 6 Km northeast of the epicenter. A team composed by the authors surveyed and inspected the earthquake damages both in Paganica, a town nearby, and L'Aquila city, from April 26 to May 2, 2009.

The structural damage ranged from several complete collapses of masonry and reinforced concrete buildings to medium damage of industrial facilities and minor paint and finish repairs for several buildings and houses. For the sake of comparison, some photos have been retrieved from Google StreetView.

ACKNOWLEDGMENTS

The team wishes to acknowledge the support, assistance, and contributions of few organizations and individuals in this investigation of the L'Aquila Earthquake.

Both the rector, Prof. D. Bassi and Prof. P. Zanon of the University of Trento, that arranged and made possible both the inspection and the visit, from which valuable information about inspections were obtained are acknowledged.


The Civil Protection of the Provincia Autonoma di Trento (PAT) is acknowledged for its support and assistance in the field.


Last but not least, the scientific and co-ordination support of The University Network of Seismic Engineering Laboratories (RELUIS) and of the Istituto Nazionale di Geofisica e Vulcanologia (INGV) sezione di Milano-Pavia are acknowledged.

²Delta Engineering. Arco (TN). Italy

³Department of Mechanics and Materials. University of Reggio Calabria. Italy


Fault lines of the affected area





 $(from \ \underline{http://earthobservatory.nasa.gov/images/imagerecords/37000/37794/italy_srtm_2009096_lrg.jpg))$


Epicentral area






(from Istituto Nazionale di Vulcanologia: http://portale.ingv.it/portale_ingv)

The seismic sequence of L'Aquila - April 2009.




(from Istituto Nazionale di Vulcanologia: http://portale.ingv.it/portale_ingv)

Durations of a ground motion record



HB060 Ground motion time histories -X, Y and Z direction accelerations at 65.9 Km Epicentral distance-

Observed 5% damped accelerations spectra and EC8 spectral shapes scaled to the PGA of the national hazard map (0.25~g) for two near-fault records belonging to soil class A and B, respectively.



(from Ameri G. et al. Istituto Nazionale di Vulcanologia: http://portale.ingv.it/portale_ingv)

Affected areas





A view of Paganica town Photo by the Provincia Autonoma di Trento (PAT) Geological Service





A view of L'Aquila city Photo by Bursi, Dusatti and Pucinotti

Geology and seismology





Paganica Photo by PAT Geological Service





PaganicaPhoto by PAT Geological Service

Reinforced concrete buildings



Reinforced concrete building in Paganica - via San Vincenzo, 9





Reinforced concrete building in Paganica - via San Vincenzo, 9





Reinforced concrete building in Paganica- via San Vincenzo






Reinforced concrete building in Paganica - Via Sant'Emidio






















Reinforced concrete building in Paganica - Via del Pianello















Reinforced concrete building in Paganica - Via L. Biordi



Reinforced concrete building in Pianola *Photo by Bursi, Dusatti and Pucinotti*









Reinforced concrete School building in Pettino Photo by Bursi, Dusatti and Pucinotti



 $\label{eq:Alighieri} \textbf{A view of buildings nearby via Dante Alighieri in Pettino (from Google Maps)}$



(from Google StreetView)







Pettino: via Dante Alighieri – Building N. 1 *Photo by Bursi, Dusatti and Pucinotti*



Pettino: via Dante Alighieri – Building N. 1 *Photo by Bursi, Dusatti and Pucinotti*









Pettino: via Dante Alighieri – Building N. 2 *Photo by Bursi, Dusatti and Pucinotti*



Pettino: via Dante Alighieri – Building N. 6 *Photo by Bursi, Dusatti and Pucinotti*



Pettino: via Dante Alighieri – Building N. 3 *Photo by Bursi, Dusatti and Pucinotti*





Pettino: via Dante Alighieri – Building N. 4









Pettino: via Dante Alighieri – Building N. 5 *Photo by Bursi, Dusatti and Pucinotti*



Reinforced concrete building in L'Aquila Photo by Bursi, Dusatti and Pucinotti





Reinforced concrete building in L'Aquila









Reinforced concrete building in L'Aquila - via XX Settembre (Student House)





Reinforced concrete building in L'Aquila - via XX Settembre (Student House)



Reinforced concrete building in L'Aquila - via Porta Napoli













Reinforced concrete building in L'Aquila - via XX Settembre





Reinforced concrete building in L'Aquila - via Giovanni XXIII (Hotel Duca degli Abruzzi) Photo by Bursi, Dusatti and Pucinotti





Reinforced concrete building in L'Aquila - via Giovanni XXIII (Hotel Duca degli Abruzzi)

commento immagini

Photo by Bursi O.S., Dusatti T. and Pucinotti R.





Masonry buildings





Masonry building in Paganica - piazza della Concezione



Masonry building in Paganica - SS 17 Bis *Photo by Bursi, Dusatti and Pucinotti*



(from Google StreetView)








Masonry building in Paganica - via San Gregorio Photo by Bursi, Dusatti and Pucinotti











Masonry building in Paganica - via San Gregorio









Masonry building in Paganica - via Castellano, 70 *Photo by Bursi, Dusatti and Pucinotti*





Masonry building in Paganica - via del Cardarello Photo by Bursi, Dusatti and Pucinotti



(from Google StreetView)






Masonry building in L'Aquila - via Ponte Rosarolo Photo by Bursi, Dusatti and Pucinotti





(from Google StreetView) Masonry building in L'Aquila - via San Gregorio







L'Aquila - Porta Napoli Photo by Bursi, Dusatti and Pucinotti









L'Aquila - Duomo Photo by Bursi, Dusatti and Pucinotti



Masonry building in L'Aquila - Piazza della Repubblica



Masonry building in Onna Photo by Bursi, Dusatti and Pucinotti

Industrial buildings



Industrial building in Bazzano *Photo by Bursi, Dusatti and Pucinotti*



Industrial Silos in Bazzano *Photo by Bursi, Dusatti and Pucinotti*













Industrial Buiding in L'Aquila Pile *Photo by Bursi, Dusatti and Pucinotti*

Wooden buildings













Wooden Buiding in Roio Piano *Photo by Bursi, Dusatti and Pucinotti*



Wooden house in Paganica - via C. Mastracci *Photo by Bursi, Dusatti and Pucinotti*

Emergency repairs by the Civil Protection of PAT




Bazzano - via Santa Giusta *Photo by Bursi, Dusatti and Pucinotti*





Bazzano - via Santa Giusta *Photo by Bursi, Dusatti and Pucinotti*



L'Aquila - Corso Vittorio Emanuele *Photo by F. Osti*









L'Aquila - Corso Vittorio Emanuele *Photo by F. Osti*

The camp of the Civil Protection of PAT @Paganica




Photo by Bursi, Dusatti and Pucinotti

The inspecting team

